








Heavily damaged pump has been restored to their original profile by using cold ceramic composite



Pump Cover has been restored to their original profile by using cold ceramic composite



Heavily damaged pump body has been restored to their original profile by using cold ceramic composite



Heavily damaged pump body has been restored to their original profile by using cold ceramic composite



TEL: 0090 532 245 11 75, 0090 506 344 80 86, 0090 216 482 45 21, 0090 482 92 73

Our composite coatings for <u>erosion-corrosion-cavitation protection</u> reduce further deterioration, increasing pump efficiency and reducing frequent maintenance costs.

